SENSORS OF HOT PLACES






HBA resistance type

Description:

Resistance temperature sensor with metal thermowell and compression fitting. You can put into boring. Connection head: plastic with jack.

Temperature: -200...+600°C, -50...+400°C



Compression fitting H B A **Ordering code: MEASURING-ELEMENT:** Pt100 Resistance type: Other Class of accuracy: \boldsymbol{A} В Other Construction: Simple Double Triple 2 wire Connection: 3 wire 4 wire Measuring of range: -200...+600° C -50...+400° C THERMOWELL, CONNECTION: Material of thermowell: 1,4301 Other Diameter of thermowell [mm]: 6 8 Other <u>Length of thermowell[mm]:</u> ACCESSORIES ON REQUEST: Not order Compression fitting: Order

Naturally, we can differ from the above construction.