SCREW-IN SENSOR







BBA resistance type

Description:

Resistance air-temperature sensor with thermowell and connection head. Thread mounting: 1/4", perforated or closed design. *Temperature*: -200...+600°C, -50...+400°C



Ordering code:



Naturally, we can differ from the above construction.