SCREW IN SENSORS







ANA resistance type

Description:

Resistance temperature sensor, where the corrosion-proofing and the quick lay-time are important. As dipping sensor in containers (in pipes with heat-insulation). Especially in the building engineering, and in the heating-, hot-water-, and climate control.

Temperature: -200...+600°C, -50...+400°C





Naturally, we can differ from the above construction.